## JHARKHAND STATE ELECTRICITY REGULATORY COMMISSION RANCHI

## FORM OF PROCEEDINGS

Case No. 26 of 2011

Prakash Tekriwal & others		 Petitioners
	Versus	
Jharkhand State Electricity Board		 Respondent

SI. No.	Date of	Proceedings of the Commission with signature	Office
	proceeding	i recodulinge of the commission with digitaters	action taken with date
1	2	3	4
2.	27.08.2011	S/Shri Ramesh Thakur, Chief Engineer (Stores &	
		Purchase) and Shri R.J. Singh, Elec. Superintending	
		Engineer (Ranchi Supply Circle) appeared on behalf of	
		the licensee-JSEB.	
		Heard.	
	The Commission by its order dated 10.8.2011		
		directed the licensee-JSEB to show-cause as to under	
		what provisions of law the licensee-JSEB is saying that	
		they will replace/repair the defective Transformers only	
		when 75% of the total dues of the consumers serviced by	
		that Transformer is received by them. Further, the	
		licensee-JSEB was also directed to send a detailed report	
		containing place/area, serial number, capacity and date	
		of failure of the Transformers and the date of	
		replacement of the failed Transformers. It was also	
		directed to inform whether the capacity of the	
		Transformers placed in the areas are sufficient to cater	
		the load of the consumers of those areas. Besides, the	
		licensee-JSEB was also directed to file updated position	
		about the replacement/repair of defective Transformers	
		of Tola Lawatu (Pundag), Boreya and Arsundey villages of	
1			

Kanke Block.

The Electrical Superintending Engineer, Elec. Supply Circle, Ranchi has filed a report stating that the Transformers of Lawatu (Pundag) and Kanke Bazartand have been replaced whereas the Transformers of Arsandey and Boreya have been repaired and rectified. The report further shows that 9 (nine) Transformers have been replaced/repaired/rectified out of Angara, Rampur, Silli, Tatisilway, Nevari, Vikash, Ratu, Prakashtah, Katamkuli, Nagri, Bajpur, Itki, Sukurhutu, Pipratoli, Pthoria, Prem Nagar (Kanke), Jate, Marangahuta, Arki, Gutjora, Gamharia, Bhandra, Murhu and the balance will be replaced very shortly.

Perused the report.

The report submitted on behalf of the licensee-JSEB is vague. The report does not show as to which place the nine Transformers have been replaced.

Further, no show-cause has been filed as to under what provisions of law the licensee-JSEB is saying that they will replace/repair the defective Transformers only when 75% of the total dues of the consumers serviced by that Transformer is received by them. The licensee-JSEB has also not submitted a detailed report containing place/area, serial number, capacity and date of failure of the Transformers and the date of replacement of the failed Transformers as also whether the capacity of the Transformers placed in the areas are sufficient to cater the load of the consumers of those areas.

The Commission feels that the concerned officers of the licensee-JSEB are very casual in their work and are not discharging their duties seriously. However, taking a lenient view, the licensee-JSEB is being given one more opportunity to show-cause by the next date on the above issues along with a detailed report as mentioned above on affidavit.

Put up on 14.09.2011 at 11.30 AM for further hearing.

Let a copy of this order be sent to the licensee-JSEB for compliance.

Sd/-Member (E) Sd/-Chairperson