JHARKHAND STATE ELECTRICITY REGULATORY COMMISSION RANCHI

FORM OF PROCEEDINGS

Case No. 26 of 2011

Prakash Tekriwal & others		 Petitioners
	Versus	
Jharkhand State Electricity Board		 Respondent

SI. No.	Date of proceeding	Proceedings of the Commission with signature	Office action taken
1	2	0	with date 4
4.	15.10.2011	Shri Ramesh Sahu and Smt. Hemlata Oraon appeared	4
7.	10.10.2011	Cim Hameon Gana and Cim. Hermata Graen appeared	
		on behalf of the petitioners. S/Shri Alok Sharan, Member	
		(Finance), S.C. Mishra, Chief Engineer (C&R), Gaya Pd.	
		Shukla, Chief Engineer, WNK Horo, Chief Engineer/S&D, R.J.	
		Singh, Elec. Superintending Engineer, Sanjay Kumar, Electrical	
		Executive Engineer, Ranchi Central appeared on behalf of the	
		licensee-JSEB.	
		The licensee-JSEB has furnished information regarding	
		replacement/repairs of defective Transformers. As per the	
	information given by the licensee-JSEB, they have replaced		
		701 Transformers in the six area Board offices from March	
		2011 to August 2011 whereas the total no. of failed	
		Transformers is 1372. It means 671 Transformers are yet to be	
		replaced/repaired. The licensee-JSEB was asked to give a time	
		frame by which they would replace/repair these failed	
		Transformers. The licensee-JSEB sought some time to work	
		out a time frame and submit to the Commission.	
		The Commission enquired as to how many	
		Transformers are reported to repairing centres and against that	
		what is the capacity of these centres. The officers of the Ranchi	
		area, who were present, informed that on an average basis 6-7	
		failed Transformers are reported daily whereas only 2-3 are	

repaired. There is obviously shortfall in repairing the failed Transformers. The Commission feels that unless adequate arrangements to repair the failed Transformers are made it will be difficult to replace the defective Transformers within the time frame given in the JSERC (Distribution Licensees' Standard of Performance) Regulations, 2005. Needless to emphasize that the Standard of Performances are mandatory for all the licensees including the licensee-JSEB to be observed otherwise compensation provisions are attracted.

On the point of payment of 75% of dues, prior to the replacement of defective transformers, it was informed by the officers of the licensee-JSEB that they were asking for payment of 75% dues from the consumers serviced by the defective Transformers on the basis of BSEB's earlier circulars. However, during the course of hearing the officers of the licensee-JSEB informed that the JSEB withdraws this plea of theirs. The Commission wants to make it very clear as already been stated in its order dated 25.3.2011 passed in Case No.01 of 2011 (M/s Kohinoor Steel Private Limited Vrs. JSEB & others) that after coming into force the Electricity Act 2003 and JSERC (Electricity Supply Code) Regulations, 2005, the BSEB's orders/circulars/Regulations/Code do not have any legal authority in Jharkhand and the licensee-JSEB cannot use them in defence of their actions.

On the point of capacity of transformers placed in the areas, to be sufficient to cater the load of consumers under that particular transformer, it is stated that most of the transformers have sufficient capacity and wherever it is not sufficient, efforts

are being made to install an additional transformer. This is a vague and evasive reply. The Commission asked the information which are the areas where existing transformer is already over-loaded. This is needed because so many transformers are failing and one of the main reasons is over-loading of such transformers. The license-JSEB is again directed to furnish the required informations by the next date.

Post this case on **05.11.2011** at **11.30 AM** for further hearing.

Sd/-Member (E) Sd/-Chairperson